
Carrier Remote IPE

CRI messages

CRI1005	SUPL XXX Local Carrier 0 Alarm Level 0 OK
CRI1006	SUPL XXX Carrier 0 MMI enabled
CRI1010	SUPL XXX Local Carrier 0 Alarm Level 1 B.E.R. Exceeded
CRI1020	SUPL XXX Local Carrier 0 Alarm Level 2 B.E.R. Exceeded
CRI1030	SUPL XXX Local Carrier 0 Alarm Level 3 B.E.R. Exceeded
CRI1031	SUPL XXX Local Carrier 0 Alarm Level 3 Frame Slip THRSH Exceeded
CRI1032	SUPL XXX Local Carrier 0 Alarm Level 3 Loss of Signal
CRI1033	SUPL XXX Local Carrier 0 Alarm Level 3 Blue Alarm
CRI1034	SUPL XXX Local Carrier 0 Alarm Level 3 Out of Frame
CRI1036	SUPL XXX Carrier 0 MMI disabled
CRI1105	SUPL XXX Local Carrier 1 Alarm Level 0 OK
CRI1106	SUPL XXX Carrier 1 MMI enabled
CRI1110	SUPL XXX Local Carrier 1 Alarm Level 1 B.E.R. Exceeded
CRI1120	SUPL XXX Local Carrier 1 Alarm Level 2 B.E.R. Exceeded
CRI1130	SUPL XXX Local Carrier 1 Alarm Level 3 B.E.R. Exceeded
CRI1131	SUPL XXX Local Carrier 1 Alarm Level 3 Frame Slip THRSH Exceeded
CRI1132	SUPL XXX Local Carrier 1 Alarm Level 3 Loss of Signal

CRI1133	SUPL XXX Local Carrier 1 Alarm Level 3 Blue Alarm
CRI1134	SUPL XXX Local Carrier 1 Alarm Level 3 Out of Frame
CRI1136	SUPL XXX Carrier 1 MMI disabled
CRI1205	SUPL XXX Local Carrier 2 Alarm Level 0 OK
CRI1206	SUPL XXX Carrier 2 MMI enabled
CRI1210	SUPL XXX Local Carrier 2 Alarm Level 1 B.E.R. Exceeded
CRI1220	SUPL XXX Local Carrier 2 Alarm Level 2 B.E.R. Exceeded
CRI1230	SUPL XXX Local Carrier 2 Alarm Level 3 B.E.R. Exceeded
CRI1231	SUPL XXX Local Carrier 2 Alarm Level 3 Frame Slip THRSH Exceeded
CRI1232	SUPL XXX Local Carrier 2 Alarm Level 3 Loss of Signal
CRI1233	SUPL XXX Local Carrier 2 Alarm Level 3 Blue Alarm
CRI1234	SUPL XXX Local Carrier 2 Alarm Level 3 Out of Frame
CRI1236	SUPL XXX Carrier 2 MMI disabled
CRI2005	SUPL XXX Remote Carrier 0 Alarm Level 0 OK
CRI2010	SUPL XXX Remote Carrier 0 Alarm Level 1 B.E.R. Exceeded
CRI2020	SUPL XXX Remote Carrier 0 Alarm Level 2 B.E.R. Exceeded
CRI2030	SUPL XXX Remote Carrier 0 Alarm Level 3 B.E.R. Exceeded
CRI2031	SUPL XXX Remote Carrier 0 Alarm Level 3 Frame Slip THRSH Exceeded
CRI2032	SUPL XXX Remote Carrier 0 Alarm Level 3 Loss of Signal
CRI2033	SUPL XXX Remote Carrier 0 Alarm Level 3 Blue Alarm
CRI2034	SUPL XXX Remote Carrier 0 Alarm Level 3 Out of Frame
CRI2105	SUPL XXX Remote Carrier 1 Alarm Level 0 OK
CRI2110	SUPL XXX Remote Carrier 1 Alarm Level 1 B.E.R. Exceeded
CRI2120	SUPL XXX Remote Carrier 1 Alarm Level 2 B.E.R. Exceeded

CRI2130	SUPL XXX Remote Carrier 1 Alarm Level 3 B.E.R. Exceeded
CRI2131	SUPL XXX Remote Carrier 1 Alarm Level 3 Frame Slip THRESH Exceeded
CRI2132	SUPL XXX Remote Carrier 1 Alarm Level 3 Loss of Signal
CRI2133	SUPL XXX Remote Carrier 1 Alarm Level 3 Blue Alarm
CRI2134	SUPL XXX Remote Carrier 1 Alarm Level 3 Out of Frame
CRI2205	SUPL XXX Remote Carrier 2 Alarm Level 0 OK
CRI2210	SUPL XXX Remote Carrier 2 Alarm Level 1 B.E.R. Exceeded
CRI2220	SUPL XXX Remote Carrier 2 Alarm Level 2 B.E.R. Exceeded
CRI2230	SUPL XXX Remote Carrier 2 Alarm Level 3 B.E.R. Exceeded
CRI2231	SUPL XXX Remote Carrier 2 Alarm Level 3 Frame Slip THRESH Exceeded
CRI2232	SUPL XXX Remote Carrier 2 Alarm Level 3 Loss of Signal
CRI2233	SUPL XXX Remote Carrier 2 Alarm Level 3 Blue Alarm
CRI2234	SUPL XXX Remote Carrier 2 Alarm Level 3 Out of Frame
CRI3301	SUPL XXX External Alarm 1 cleared
CRI3302	SUPL XXX External Alarm 2 cleared
CRI3303	SUPL XXX External Alarm 3 cleared
CRI3311	SUPL XXX External Alarm 1 Set
CRI3312	SUPL XXX External Alarm 2 Set
CRI3313	SUPL XXX External Alarm 3 Set
CRI4437	No response or the response was too slow (software timed out to avoid INIT within INIT) from the carrier hardware during Carrier Remote Interface initialization update. If the message is output again with the same loop number, then it is an indication that there is a hardware fault in either the LCI or RCI card.